Simulator - HDMI Display Mode - NGC

haascnc.com/service/troubleshooting-and-how-to/how-to/simulator---hdmi-display-mode.html

Recently Updated

Revision 1

Introduction

This procedure will show you how to connect your simulator to a HDMI monitor device. This will allow you to view the simulator display on a TV, PC monitor, projector, etc.

Software Compatibility:

Software version 100.19.000.1200 or higher.

Simulator with A62 Main Board PCB

A62 Mainboard PCB

Monitor

1

Power OFF the Simulator.

Remove the back cover.

Remove one of the empty plugs. Feed the HDMI cable through the hole.

Connect a standard HDMI cable between the HDMi connector on the Main board and the HDMI monitor.

Simulator with Q7 Maincon PCB

Q7 MainCon PCB

Monitor

1

Power OFF the Simulator.

Remove the back cover.

Remove one of the empty plugs. Feed the HDMI cable through the hole.

Connect a standard HDMI connector J4 on the Mainboard PCB.

Power On in HDMI Mode

Press and hold the **'H'** key while booting for **HDMI mode**.

Note: The next time the simulator or machine is powered on the simulator will boot into the standard display option.